



FIELD MODIFY SHEAR PLATES FURNISHED WITH C6 GIRTS TO SUIT

CHICAGO METAL NOTE:  
 THE COLUMNS MUST BE BENT TO THE CURVATURE SHOWN ON THE LAYOUT TITLED 06-11 WORKING PTS A. ADD TANGENTIAL EXTENTS AS SHOWN HERE TO COMPLETE THE LENGTHS REQUIRED.

FIELD BOLTS		4-3/4 F1852 x 2						
NO REQ'D	MARK	DESCRIPTION	UNIT WT	LGTH FT	INS	TOTAL WEIGHT	REMARKS	P L
1		ONE-3C1 (COLUMN WEST)						
2	1	HSS8.625 x 0.322	28.58	17	7±	503	S.I.E. ROLLED	
3	1	CB2 PL <sup>3</sup> 4x14 (A36)	35.8	1	4	48		
4	1	Pa3 PL <sup>1</sup> 2x10 (A36)	17	1	5	24		
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								

ONE - COLUMN - 3C1 (COLUMN WEST)

Q.C.	PASSED	REJECTED
HEAT # (IF REQ'D)		
A6 SWEEP		
A6 CAMBER		
ALL DIMENSIONS		
GRADE		
BOLTS		
WELDS		
SURFACE PREP		
PAINT		
FABRICATOR		
TIME START/STOP		
INSPECTOR		DATE

12/09/13 - REVISE AND ADD DIMS.

STANDARD IRON WORKS

CONTRACT No 739

CUSTOMER GIVONEHOME  
 STRUCTURE FALLS FARMHOUSE

DWG BY RGY

Checked SAI